

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Amendment to the Drawings

The attached sheets of drawings include changes to Figs. 1, 2A, 2B, 4A, 7A, and 7B.

In Fig. 1, "Fan FB1" in power supply B0 has been changed to --Fan FB0--, "Fan FB1" in power supply A1 has been changed to --Fan FA1--, and "Fan FB1" in power supply A0 has been changed to --an FA0--.

In Figs. 2A and 2B, reference numeral 201 has been added.

In Fig. 4A, reference numeral 404 has been added.

In Fig. 7A, reference numeral "Midplane board 106" has been added.

In Fig. 7B, reference numeral "Disk drives 1 to 3" has been changed to --Disk drives 1 to 4--.

Attachment: Replacement Sheets 1, 2, 5, 8, and 9.




FIG. 1





"Isolation of I2C Buses in a Multiple Power Domain Environment Using Multiplexers

Inventor: William J. Price

Docket No.: 3PD-M-8502 US

Replacement sheet 2/11





"Isolation of I2C Buses in a Multiple Power Domain Environment Using Multiplexers

Inventor: William J. Price

Docket No.: 3PD-M-8502 US

Replacement sheet 5/11

FIG. 4A




FIG. 4A



"Isolation of I2C Buses in a Multiple Power Domain Environment Using Multiplexers

Inventor: William J. Price

Docket No.: 3PD-M-8502 US

Replacement sheet 8/11

FIG. 7A
FIG. 7B
FIG. 7C




FIG. 7A




FIG. 7B